

MISSOURI DEPARTMENT OF HEALTH STATE PUBLIC HEALTH LABORATORY

DATAMASTER MAINTENANCE REPORT

RECEIVED DHSS Breich Alsehol Program
By Carol Day at 8:00 am, Mar 15, 2010

Complete this report in duplicate at the time is repaired. Send copy to Department of Health	of the regular monthly preventive retain original in department file.	maintenance check, and whenever instrumen	
204063 / NV# 127190	DATE OF INSPECTION 3.5.2010		
MARIES COUNTY SHERIFF'S DEPT. VIENNA, MO		TIME OF INSPECTION	
CHECKLIST: Place a check (✓) to the left of e in observed values where determined.) Uncheck	ach item if found to be satisfactory	or if operating within established limits. (Write	
DIAGNOSTIC CHECK (PRINTOUT ATTAC	HED)		
⊠ COMPUTER	☐ DETECTOR		
⊠ PROGRAM	⊠ FILTERS	☐ FILTERS	
HEATERS SAMPLE CHAMBER 50	_°C Quartzstan	NDARD	
FLOW DETECTOR	🖺 CALIBRATION		
D PUMP HIGH SPEED	□ PRINTER		
M INDICATOR LIGHTS			
TIME AND DATE 3.5.2010 @ 19;	37		
SIMULATOR TEMPERATURE (34 °C ± 0.2°		117	
☑ CALIBRATION CHECK -) 3.70. 6-1		
	All three tests would be 2005		
spread of .005 or less. Check the box corre	sponding to the standard solution	5% of the standard value and must have a being used. (PRINTOUT ATTACHED) (USE	
☑ 0.100% STANDARD - MUST READ BETV	VEEN 0.095% and 0.105% INCLUSIV	F	
⊕ 0.040% STANDARD - MUST READ BETV (ONLY ONE STANDARD IS TO BE USED P	VEEN 0.038% and 0.042% INCEUSIV	E'	
TEOTA .	T2 . 096	TEST 3 . 097	
PERFORM R.F.I. TEST (PRINTOUT ATTACH	IED)		
NUMBER OF REFUSALS, SINCE LAST MAIN FOLLOWS: , (DO NOT INCLUDE SIMULATE	ITENANCE REPORT, AND NUMBER	R OF BREATH TESTS IN EACH RANGE AS	
\int_{-1}^{1}		(.1519) Z (Over .19)	
ist any new parts and describe any alteration of	or modification that was made to re-	store the instrument to operate satisfactorily	
and within colubined limits tuse office sine it her	Passaru)		
THIS INSTRUMENT OPERATES WITHIN -	THE DEPT. OF HEALTH &	ENIVE SERVICES SAFE	
		January Jacob	
NSPECTING OFFICER			
IGNATURE CAST	PRINT NAME		
1485.18 Bloods		B. M. VOLT, TRUPER # 997	
YPE 11 PERMIT NUMBER/ÉXPIRATION DATE 920091	TELEPHONE NUMBER	TELEPHONE NUMBER	
[CU U - (]	(573) 368-2.	(573) 368-2345	

REPCO MARKETING INC.

\$101-188 STONYERGON DRIVE RALLIGH, N.C. 27604 819-870-9460

P 2/2

CERTIFICATE OF ANALYSIS

MANUFACTURER AND SUPPLIER: RepCo Warketing, Inc.

LOT NUMBER: 09001

EXPIRATION DATE: April 22, 2011 at 11:59 p.m.

RepCo Marketing, Inc. certifies the following:

RepCo Marketing, Inc. manufactured, tested and supplied Lot Number 09001 of Alcohol Certified Solution for simulators. Random samples of said lot number were analyzed by an independent laboratory utilizing a gas chromatograph and found to contain ___1214_ gms/dl +/-_003 gms/dl wt/vol ethanol (95% Confidence).

The alcohol and distilled water used in the solution were found to be free of any interfering substance.

This solution will produce a vapor alcohol value of .100 +/-3% gms/210L Breath when heated to 34 Degrees Celsius +/-0.2 Degrees Celsius in a simulator (95% Confidence).

The date of manufacture for this lot number is April 23, 2009, The expiration date for this lot number is at 11:59 p.m.

This document is a true representation of the original Certificate of Analysis,

> Cecil B. Garner, President RepCo Marking, Inc.

State of Missouri DEPARTMENT OF HEALTH



PERMIT TYPE II



BROCK A VOGT

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field repairs, and operate the following breath analyzer(s):

DATAMASTER

for the determination of the alcoholic content of blood from a sample of expired (alveolar) air. Issued under the provisions of sections 577.020 through 577.041, RSMo 1986.

air. Issued under the provisions of se	ections 577.020 through 577.041, RSMo 1986.
Date04/22/09	John of Mathewson
920091	Director of State Public Health Laboratory
	Margart T. Dannelly
Expires	
NO 500 0774 47 000	Director, Department of Health Lab. 4 (87-88)
MO 580-0771 (7-88)	LAD. 4 (71/-00

Face This Side Down - This Edge In First

BAC DataMaster Evidence Ticket

MISSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL NUMBER 204063 03/05/10 19:37

---- BINGNOSTIC CHECK ---

COMPUTERS

OKAY

PROBREM (04-87-2669):

OKAY

HEATERS

SHAPLE CHAMBERS

Side

FLOW DETECTORS

UKEY

FUN

HIGH SPEED:

的缺陷等

DETECTORS

ÖKAY

FILTERS:

DICAY

QUARTE STANDARDS

OKAY

CALL BEHILDON:

BEHT!

PRINTER TEST

!"#%%%'()#0.-.20123456789:;(=>?@ABCOEFG HIJKLMNOPOHS?UVWXYZ[\]r_'abcdetghijklmno pgrszuwwwgg(())*

Operator Signature

Face This Side Down - This Edge In First

BAC DataMasterEvidence Ticket

MISSOUR) STATE HIGHWAY PATROL DAC DATAMASTER SERIAL NUMBER 204063 03/05/10

TESTING OFFICER:
VOGT/EROCK/Fi
OFFICER I.D.: 997
PERMIT MUMBER: 920091
EXPIRATION DATE: 84/22/11
MISCELLANEOUS DATE:

--- SUPERVISON NODE ---

BLANK TEST	, ove	19:45
INTERMAL STANDARD	VER171ED	19:45
EXTERMOL STREBARD	. (1971	19:45
BLANK TEST	. OHO	19:46
EXTERMAL STAMBARD	. 996	191147
BLANK TEST	. 9(96)	19447
EXTERNAL STANDARD	. 997	19865
BLAHK TEST	. 896	19:45

n = 3 | SIM. = .1 | AVB. = .8966

Operator Signature

2208-0

Face This Side Down - This Edge In First

BAC DataMasterEvidence Ticket

MISSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL NUMBER 204063 93/05/10 19:37

-- DIMANOSTIC CHECK ---

COMPUTER:

ÜKAY

PALIGRAM (84-87-2689):

KAY

HEATERS

SAMPLE CHAMBER:

Sec

FLOW DETECTOR:

. Cik läiz

PUMP

HIGH SPEED:

WAY.

DETECTORS

DKAY

FILTERS:

UKAY

QUARTZ STANDARD:

OKEY

CALIBRATIONS

OKMY

PRINTER TEST

"##XE(C)++,-./0123456789:(<=>/@FBCDEF0 HIJKLTHOPORSTUVWXYZL\I^_\abddefghijk\mno pgrstuvwxyz(1)+

Operator Signature

2208-02